

Type of Notification: Product Discontinuation

FIRST ISSUE DATE	REISSUE DATE	LAST BUY DATE	NOTIFICATION NO.	LAST SHIP DATE
31 July 2009	9 December 2009	1 August 2009	PCN-20090731-01-R	21 August 2009

*This is to advise you that the following products have been discontinued.
This PCN has been revised: Language has been edited.*

Product ID (Description):

LCD Modules affected (see list on Page 2)

Description of Change:

Sharp Microelectronics of the Americas (SMA) will no longer be selling certain LCD Modules in the United States. Deliveries for these items will occur through 21 August 2009. After that date, all U.S. deliveries will cease; customers may not request deliveries beyond this date from SMA. These parts may continue to be available globally from other Sharp International Business Units.

Many modules have replacement parts immediately available; some replacement parts will be available shortly; other parts will have no replacements. Please see the list beginning on Page 2 of this document.

Effect of Change:

The LCD modules listed on Page 2 are no longer sold in the United States as of August 24, 2009. Please see the list on Page 2 for the specific part numbers and their replacement part numbers.

Suggested Alternate Parts and/or Manufacturers:

DISCONTINUED SHARP PART NO.	SUGGESTED ALTERNATE PART NO.	ALTERNATE MANUFACTURER
SEE LIST	SEE LIST	SEE LIST

Customers must notify Sharp Microelectronics of the Americas in writing 90 days before the last buy date if they consider the discontinued product to be "Single Source". Sharp Microelectronics of the Americas and the customer may negotiate an appropriate End-of-Life Agreement.

In case of further questions, please contact your Sharp sales representative.

Affected Part Numbers:

PART NUMBER	REPLACEMENT PART NUMBER	SAMPLE DATE	MANUFACTURING START
LQ042T5DZ01	LQ042T5DZ01	—	—
LQ043T3DX02	LQ043T3DX02K	9/30/2009	9/30/2009
LQ043T3DX04	LQ043T3DX04K	9/30/2009	9/30/2009
LQ104V1DW02	LQ104V1DW02K	8/7/2009	11/23/2009
LQ121S1LW01	NONE	—	—
LQ150X1LW71N	LQ150X1LW73	9/14/2009	12/31/2009
LQ150X1LW72			
LQ150X1MW21	NONE	—	—
LQ190E1LW43	LQ190E1LW43K	9/30/2009	1/30/2010
LQ201T1LZ01	NONE	—	—
LQ201U1LW11	NONE	—	—
LQ201U1LW11Z	NONE	—	—
LQ201U1LW21	NONE	—	—
LQ281L1LW14	LQ281L1LW14x	10/19/2009	4/1/2010
LK315T3LA24	No Immediate Replacement	—	—
LQ370T3LZ39	NONE	—	—
LQ445D3LZ19	NONE	—	—
LK460D3LZ19	To Be Determined	To Be Determined	Second Quarter, 2010
LK520D3LZ89	To Be Determined	To Be Determined	Second Quarter, 2010
LK645D3LZ29	LK600D3LAxx	11/2009	12/2009
LK645D3LZ2U	To Be Determined	To Be Determined	Second Quarter, 2010
LK645D3LZ69	LK600D3LAxx	11/2009	12/2009